

Reference: **TB 0191 (08/2025)**

Technical Bulletin

Product: CL7000i

INCORRECT TECHNICAL INFORMATION IN THE INSTALLATION MANUAL.

Please find below an update to the information supplied in the CL7000i installation instructions. The installation manual will be updated to follow the new guidelines in due course.

- Current incorrect installation manual information:

Outdoor unit	CL7000i 26 E 7733702575	CL7000i 35 E 7733702577	CL7000i 53 E 7733702581
Max power input (W)	2300	2950	2950
Max current (A)	13	13.5	13.5
Mains fuse protection	13A	13A	16A

- Correct information to use:

Outdoor unit	CL7000i 26 E 7733702575	CL7000i 35 E 7733702577	CL7000i 53 E 7733702581
Max power input (W)	2300	2950	2950
Max current (A)	13	13.5	13.5
Mains fuse protection	16A	16A	16A

The manuals will be updated to follow this information as soon as possible.

Whilst any installations that are fitted with 13A fuse protection at the consumer unit will remain safe, there is a small possibility that the fuse could blow under certain conditions. In the event of a 13A fuse blowing; to prevent future nuisance failure of the fuse, it should be replaced with a fuse rated at the recommended 16A.

Whilst it is always our intention to fully assist, it is essential to recognise that all information given by the company in response to an enquiry of any nature is provided in good faith and based upon the information provided with the enquiry. We recommend that advice should always be checked with your installer or contract partner. Consequently, the company cannot be held responsible for any liability relating to the use or repetition of such information or part thereof. In addition, whilst making every reasonable effort to monitor the performance and quality of our supply, installation and service network, we do not accept responsibility for the workmanship or operation of any third party company that the company may have promoted either in conversation, e-mail, or other communication. Similarly, the views and opinions expressed in communication with individuals within the company may not reflect that of the business as a whole.

For all issued technical bulletins, visit the Worcester Bosch website at: www.worcester-bosch.co.uk/tb or www.worcester-bosch.ie/tb